
VILLAGE OF VARNA AUGUST NEWSLETTER



NOTICE

The Village will be Flushing Hydrants once a month till further notice. Please watch for Postings and Alerts for days and dates that this will happen.



Remember

Apply For or Renew your Non-Highway Vehicle Permits Permit Applications are at villageofvarna.com Or request one 309-238-2242



Please

Follow signage at the dump when disposing yard waste.
It matters if it is burnable or compostable and creates more work if it must be sorted out of the wrong pile.
Thank You

Alerts and Notifications, such as Boil Orders and Water Disruptions or Hydrant Flushing, can be received by Subscribing at villageofvarna.com.

Newsletters, with matters of importance will be sent with Water/Garbage Bills. All happenings and postings can be found on villageofvarna.com.

Mayor: Clerk:

Louis Holocker Wendy Todd

Treasurer: Teryl Holocker

villageofvarna@yahoo.com villageofvarnaclerk@gmail.com 309-238-2240 309-238-2242

villageofvarnatreasurer@gmail.com

309-238-2241

All New ordinances will be posted on the village website after approved at the monthly Board meetings. See image below for instructions on where to find the Ordinances on the village website www.villageofvarna.com.



Community Events



Mayor: Clerk:

Louis Holocker Wendy Todd Treasurer: Teryl Holocker

villageofvarna@yahoo.com villageofvarnaclerk@gmail.com villageofvarnatreasurer@gmail.com 309-238-2240 309-238-2242 309-238-2241 **Mandated State Lead Water Line Survey**

RESPONSE REQUIRED

All Water Customers Must
Schedule a Service Inspection of
The Water Line that Services Your Home or
Business.

Report all properties if you own multiple.

Are your Water Lines Galvanized,

Copper or Plastic?

Please call Joe Glynn @TEST 815-252-9626 or 2323

If you need assistance or have questions, call the Varna Water Department 309-238-2241 or 815-760-1644



512 Main Varna

Unsure or Cannot Schedule an Inspection

Text or email a Clear Picture of the Water Line that comes into your property. Label with House Number, Street & Village.

villageofvarnawater@gmail.com

Failure to Develop Initial Inventory or make publicly accessible for Service Line Materials or Make Publicly Accessible

IMPORTANT INFORMATION ABOUT YOUR DRINKING WATER

Varna Failed to Develop and Make Public an Initial Service Line Inventory

Our water system recently violated a drinking water requirement. As our customers, you have a right to know what happened, what you should do, and what we did (are doing) to correct this situation.

We were required to develop and make publicly available an initial inventory of service lines connected to our distribution system by October 16, 2024. Our system failed to submit this initial inventory of service lines to the Illinois EPA by October 16, 2024. The inventory must identify the service line materials as lead galvanized requiring replacement (GRR)¹, lead-status unknown/unknown, or non-lead. Identifying and ultimately removing lead and GRR service lines is an important way to protect public health.

There is the potential your service line could be made of lead or contain lead. People living in homes with service lines that are made of or contain lead have an increased risk of exposure to lead from their drinking water.

"Exposure to lead in drinking water can cause serious health effects in all age groups. Infants and children can have decreases in IQ and attention span. Lead exposure can lead to new learning and behaviDr problems or exacerbate existing learning and behavior problems. The children of women who are exposed to lead before or during pregnancy can have increased risk of these adverse health effects. Adults can have fncreased risks of heart disease, high blood pressure, kidney or nervous system problems."

What should I do?

Listed below are some steps you can take to reduce your exposure to lead:

- Learn what your service line material is. Contact Village Hall at 309-238-2241 or a licensed plumber to determine if the pipe that connects your home to the water main (called a service line) is made from lead, galvanized, or other materials. Protect Your Tap: A quick check for lead is the EPA's online step by step guide to learn how to find lead pipes in your home (www.epa.gov/Pvt).
- Learn about construction in your neighborhood. Unless your service line is not made of lead
 or galvanized you should be aware of any nearby construction or maintenance work that could
 disturb the line. Ground tremors from construction may suddenly cause more lead to be
 released from lead or galvanized service lines in the area.
- Use your filter properly. Using a filter can reduce lead in drinking water. If you use a filter,
 make sure you use a filter certified to remove lead. Read the directions to learn how to properly
 install and use your cartridge and when to replace it. Using the cartridge after it has expired can
 make it less effective at removing lead. Do not run hot water through the filter.

^{*} A galvanized requiring replacement service line is a galvanized service line that is or was potentially downstream of a lead service line.

- Clean your aerator. Regularly remove and clean your faucet's screen (also known as an aerator).
 Sediment, debris, and lead particles can collect in your aerator. If lead particles are caught in the aerator, lead can get into your water.
- Use cold water. Use only cold water for drinking, cooking, and making baby formula.
 Remember, boiling water does not remove lead from water.
- Run your water. The more time water has been sitting in pipes, the more lead it may contain.
 Before drinking, flush your home's pipes by running the tap, taking a shower, doing laundry, or doing a load of dishes. The amount of time to run the water will depend on whether your home has a lead service line or not, and the length of the lead service line. Residents should contact their water utility for recommendations about flushing times in their community.
- Have your water tested. Contact your water utility to have your water tested and to learn more about the lead levels in your drinking water.

What does this mean?

Service line inventories are the foundation from which water systems take action to address a significant source of lead in drinking water. Establishing an inventory of service line materials and identifying the location of lead and GRR service lines is a key step in getting them replaced and protecting public health. Typically, lead enters water supplies by leaching from lead pipes, brass faucets, plumbing with leaded solder, and other plumbing components containing lead. In homes with lead pipes that connect the home to the water main, also known as lead services lines, these pipes are typically the most significant source of lead in the water. Lead pipes are more likely to be found in older cities and homes built before 1986. Service lines made of galvanized iron or steel that are (or were previously) downstream of lead service lines are classified as galvanized requiring replacement (GRR) because galvanized service lines that are or ever were downstream from an LSL can absorb lead and contribute to lead in drinking water. Identifying and ultimately removing lead and GRR service lines is an important way to protect public health.

What is being done?

A Service Line Material Inventory was previously submitted for Varna. An updated version is being prepared and will be resubmitted.

For more information on reducing lead exposure around your home/building and the health effects of lead, visit EPA's Web site at http://www.epa.aov/lead or contact your health care provider.

For more information, please contact Joe Glynn at 815-252-9626 or 2323 Fourth Street, Peru, IL 61354.

"Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail."

This notice is being sent to you by the Village of Varna. Public Water System IDff: IL1230300

Date distributed: 8/1/2025